

South Building - North Side Balconies - Quantities						
Unit Number	Floor Finish	Sliding Glass Door Condition	Replace Sliding Glass Door	Remove Reinstall Sliding Glass Door	Weather Walls (LF)	Shutters
602	Coating	Newer				None
502	Coating	Newer				None
402	Coating	Older/Poor	2		10	None
302	Coating	Older/Poor	2		20	None
202	Coating	Older/Poor	2			None
102						
604	Coating	Fair		1	10	None
504	Tile	Fair				Accordion at Door
404	Coating	Fair		1	10	None
304	Coating	Newer/Good		1	10	None
204	Coating	Newer			10	None
104				1	10	
606	Coating					None
506	Tile					Accordion at Door
406	Coating	Newer/Fair		1	10	
306	Tile	Newer/Fair		1	10	None
206	Coating	Newer		1	10	None
106	Coating	Older/Poor		1	10	None
608	Coating	Newer/Fair				Roll Down at Door
508	Coating	Newer/Fair				None
408	Coating	Fair				None
308	Coating		1			None
208	Coating			1	10	
108		Older/Poor	1		10	
610	Tile	Newer/Fair		1	10	Roll Down at Door
510	Coating	Older	1		10	None
410	Tile					
310	Coating	Older	1			None
210	Coating	Older/Poor	1		10	None
110						
612	Tile	Newer				
512	Coating					None
412					16	
312	Coating	Newer				None
212						
112						
614	Coating	Older	1		10	None
514	Coating	Newer		1	10	None
414	Coating	Older/Poor	1		10	None
314	Coating	Fair		1	10	None
214	Coating	Older/Fair		1	10	None
114	Tile	Newer	1		10	None
616 E						
516 E						
416 E						
316 E	Tile					
216 E						
116 E						
616 N	Coating	Older/Poor	2			None
516 N						
416 N	Coating	Newer				None
316 N						
216 N	Tile	Fair				
116 N		Newer				
Totals					246	

36